

Resurvey of Exteriors of T. 30 S., R. 4 W.

CHAINS

Timber, mostly Oak, few Laurels, Fir, Maple and Ash.
Undergrowth, young Oak.

Exterior Boundaries of T. 30 S., R. 3 W.,
As surveyed by William M. Bushey, Deputy Surveyor, under
Contract No. 620, dated June 17, 1893.

I begin at the cor. to Tps. 30 and 31 S., Rs. 3 and 4 W.
which is a post, 4 ins. sq., firmly set, marked,
T 30 S S 31 on NE R 3 W S 6 on SE T 31 S S 1 on SW
and R 4 W S 36 on NW faces with 6 notches on each edge,
from which

A Laurel, 9 ins. diam., (12 ins. now) bears N.60°E.,
34 lks. dist., marked T 30 S R 3 W S 31 B T.

A Fir, 12 ins. diam., bears S.51°E., 45 lks. dist.,
marked T 31 S R 3 W S 6 B T.

A Laurel, 9 ins. diam., bears S.31°W., 40 lks. dist.,
marked T 31 S R 4 W S 1 B T.

A Laurel, 9 ins. diam., bears N.16°W., 50 lks. dist.,
marked T 30 S R 4 W S 36 B T.

From this cor. I run E. on a random line between said
Tps., the variation of my compass being 19½°E. I set
temporary half-mile and mile cor. at each 40 and 80
chs. and at 6 miles 5 chs. and 14 lks. I set temporary
post.

October 1, 1893.

I am unable to find the ¼ sec. cor. or either of the
witness trees on the East boundary of sec. 25 T 30 S R
3 W. I find the 4 witness trees to the cor. to secs.
19, 24, 25 and 30 but the cor. has been destroyed.
At cor. point I set an Oak post, 4 ft. long, 4 ins. sq.,
24 ins. in the ground, for cor. to secs. 19, 24, 25
and 30, marked T 30 S S 19 on NE R 2 W S 30 on SE
R 3 W S 25 on SW and S 24 on NW faces, with 4 notches on