

## Exterior Boundaries of T. 30 S., R. 3 W.

CHAINS		
	Dense undergrowth of Vine Maple, Laurel, Hazel, Huckleberry, Arrowwood, Hemlock and Fir. 85.60 chs. October 5, 1893.	
	As the line between sec. 19 and 24 on the East boundary of township is an old line over which fires have burned since survey making it difficult to find the corners I therefore begin at cor. to secs. 19, 24, 25 and 30.	
	Thence I run.	
	North, on a blank line between secs. 19 and 24. Va. 19½°E	
	Ascend timber and brush.	+300
8.75	Leave timber and brush.	
32.50	Top of ridge, course NE. and SW. Enter heavy timber and descend.	-175
40.15	I find the ¼ sec. cor greatly decayed with marks nearly obliterated, 24 lks. W. of my line, I find one witness tree at cor. point. I set a Cedar. post, 4 ft. long, 4 ins. sq., 24 ins. in the ground, for ¼ sec. cor., marked ¼ S. on W. face, from which A Laurel, 24 ins. diam., (30 ins. now.) bears S.38°E., 40 lks. dist., marked ¼ S B T. This is the original witness tree. I mark A Fir, 8 ins. diam., bears S.50°W., 18 lks. dist., marked ¼ S B T.	
43.75	A stream, 2 lks. wide, course NW. Ascend.	+25
44.75	Descend.	-200
63.10	A stream, 1 lk. wide, course NW. Ascend.	+50
69.60	Trail, course NW. and SE. Descend.	-150
78.95	A stream, 2 lks. wide, course NW. Ascend.	+40
80.11	Set temp. post, I find 4 witness trees but the tree cor. is destroyed by fire and the roots burned out of the	