



Exterior Boundaries of T. 30 S., R. 3 W.

CHAINS

ground, at cor. point, I set a Cedar post, 5 ft. long, 4 ins. sq., 24 ins. in the ground, for cor. to secs. 13, 18, 19 and 24, marked T 30 S S 18 on NE R 2 W S 19 on SE R 3 W S 24 on S W and S 13 on NW faces, with 3 notches on N. and S. edges, from which

A Fir, 30 ins. diam., bears N.2\*E., 8 lks. dist., marked T 30 S R 2 W S 18 B T.

A Fir, 12 ins. diam., bears S.5\*E., 65 lks. dist., marked T 30 S R 2 W S 19 B T.

A Cedar, 5 ins. diam., (10 ins. now) bears S.60\*W., 25 lks. dist., marked T 30 S R 3 W S 24 B T.

A Fir, 12 ins. diam., bears N.55\*W., 58 lks. dist., marked T 30 S R 3 W S 13 B T.

I measure W. 20 lks. to temp. post.

Land, mountainous. 80.11 chs.

Soil, 3rd rate.

Heavily timbered with Fir, Laurel, Oak, Cedar and Maple. 56.25 chs.

Dense undergrowth of Vine Maple, Oak and Laurel, Hazel, Arrowwood, Cedar and Fir. 50.00 chs.

North, between secs. 13 and 18.

Va. 19\*E

	Ascend in timber and brush.	+40
2.40	Top of ridge, course NW. and SE. Descend.	-50
5.60	A ravine, course NW. and SE. Ascend.	+50
6.75	A Fir, 24 ins. diam., on line marked with 2 notches on N. and S. sides.	
10.50	Top of ridge, course NW. and SE. Descend.	-250
11.69	A Fir, 12 ins. diam., on line marked with 2 notches on N. and S. sides.	
21.40	A stream, 2 lks. wide, course N.10*W.	
28.25	Same stream, course N.15*E. Ascend.	+25