

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 30 S., R. 4 W.

CHAINS	<p>No other trees in reasonable distance.</p> <p>Made trench as per instructions.</p> <p>Soil, 2nd rate; high hilly land.</p> <p>Timber, Oak openings.</p> <p>T. Weaver's house S.74*W.</p> <p>I. Thorn's house N.47*W.</p>
	Var. 18*10'E.
	East, on random between Secs. 9 and 16.
40.00	Set temp. $\frac{1}{2}$ Sec. post.
80.48	Intersected E. bdy. 48 lks. N. of Sec. Cor.
	S.89*39'W., on true line between Secs. 9 and 16.
2.25	Right bank S. Umpqua, course N.79*W.
	Chained across river.
6.50	Left bank of river.
40.24	Set $\frac{1}{2}$ Sec. post at average distance, from which
	A W. Oak, 4 ins. diam., bears S.35*W., 62 lks. dist.
	A Laurel, 7 ins. diam., bears N.5*W., 35 lks. dist.
80.48	To Sec. Cor.
	Soil, 2nd rate.
	Timber, Oak openings with scattering Pine.
	August 22, 1854.
	North, between Secs. 8 and 9.
3.50	Entered bottom prairie, bears NE. and NW.
39.00	Entered scattering Oak timber
40.00	Set $\frac{1}{2}$ Sec. post, from which, Thorn's house S.60*W.
	A B. Oak, 30 ins. diam., bears S.45*W., 45 lks. dist.
	An Alder, 8 ins. diam., bears N.55*E., 50 lks. dist.
43.00	Left bank S. Umpqua, course N.71*W.
	Chained across river
46.75	Right bank of river. Bickworth's house N.68*W.
48.25	Entered prairie NW. and SE.

-20

level

-20

level

level