

County Surveyor's Record, Douglas County, Oregon

Resurvey of Exterior Lines, T. 30 S., R. 4 W.
Offset Meridian through T. 30 S., Rs. 4 and 5 W.

CHAINS

- 70.50 Leave low bottom; ascend table land, 15 ft. high.
- 80.03 Intersect S. Bdy. of Sec. 13, 4 lks. West of Sec. Cor. to Secs. 13, 18, 19 and 24. The post to Cor. being gone, but the original bearing trees still standing, I restore this corner by setting basalt rock, 10x8x7 ins., 7 ins. in the ground, marked with 3 notches on the N. and S. edges, and raise a mound of stone, 36 ins. sq. and 24 ins. high, along side; pits impracticable, from which
- A B. Oak, 24 ins. diam., bears S.68*W., 131 lks. dist., marked T 30 S R 5 W S 24 B T.
- A B. Oak, 22 ins. diam., bears N.2*E., 135 lks. dist., marked T 30 S R 4 W S 18 B T. (the field notes of original survey make this B T bear N.20*E., which is undoubtedly an error.); I re-mark the same, as the marks are overgrown.
- Land, N. of river, mountainous; land, S. of river, level prairie.
- Soil, N. of river; rocky, 3rd rate.
- Soil, S. of river; rich loam, 1st rate.
- Timber, a few Oaks and Firs.
-
- Var. 17*28'E.
- South, bet. Secs. 19 and 24.
- Level prairie but gravelly.
- 9.50 A run, 2 lks. wide, course NW.
- 25.00 Enter young Oak timber; leave prairie.
- 31.50 Leave Oak timber; enter prairie.
- 40.02 Branch, 7 lks. wide, course NW.
- 40.10 $\frac{1}{4}$ Sec. Cor., bears W. 15 lks. Post gone, bearing tree in Sec. 24 blown down; in Sec. 19 standing. I restore this Cor. by setting a W. Oak post, 3 ft. long, 3 ins. sq., 24 ins. in the ground, marked $\frac{1}{4}$ S on W. face,