

County Surveyor's Record, Douglas County, Oregon

Resurvey of Exterior Lines of T. 30 S., R. 4 W.
Offset Meridian through T. 30 S., Rs. 4 and 5 W.

CHAINS 17.00	Top of spur, course W.; begin descent.	
21.00	Enter Oak openings.	
35.00	Enter rolling prairie.	
40.05	<p>$\frac{1}{4}$ Sec. Cor. bears W., 12 lks. dist. I find an old post in place, but not the original one. I replace the same with a W. Oak post, 3 ft. long, 3 ins. sq., 12 ins. in the ground, and set in a mound of stone, from which</p> <p>A W. Oak, 30 ins. diam., bears S.30'W., 400 lks. dist., marked $\frac{1}{4}$ S B T.</p> <p>A B, Oak, 24 ins. diam., bears S.5'E., 500 lks. dist., marked $\frac{1}{4}$ S B T.</p> <p>These are the old bearing trees, which I re-mark, as the old marks are overgrown.</p>	-120
45.00	Leave prairie; enter Oak openings.	
50.00	Leave Oak timber for Fir timber and heavy underbrush; begin ascent.	
60.92	Fir, 48 ins. diam., re-mark same.	
69.00	Very steep ascent.	
77.00	Top of ridge, course E. and W.; enter burn.	+700
80.15	<p>Intersected S. Bdy. of Sec. 30, 22 lks. E. of Cor. to Secs. 25, 30, 31 and 36</p> <p>The post set for this corner is gone but the bearing trees in Secs. 30 and 36 are standing. The Laurel, 4 ins. diam., in Sec. 31 is killed by fire, and the Fir, 48 ins. diam., is fallen, corresponding in direction and distance with the one described in field notes furnished me. I restore this corner by setting a B. Oak post, 4$\frac{1}{2}$ ft. long, 4 ins. sq., 24 ins. in the ground, marked T 30 S S 30 on NE., R 4 W S 31 on SE., R 5 W S 36 on SW., S 25 on NW. faces with 5 notches on N. and 1 notch on S. edges, from which</p> <p>A Laurel, 8 ins. diam., bears N.82'E., 57 lks. dist., marked T 30 S R 4 W S 30 B T.</p> <p>A Fir, 20 ins. diam., bears S.18'W., 35 lks. dist., marked T 30 S R 5 W S 36 B T.</p>	-25