

County Surveyor's Record, Douglas County, Oregon

Resurvey of Exterior Lines of T. 30 S., R. 4 W.
Offset Meridian through T. 30 S., Rs. 4 and 5 W.

CHAINS 48.00 54.84 62.90 68.00 80.10	<p>Enter old Fir timber, bears E. and W.</p> <p>A Cedar, 30 ins. diam.</p> <p>Branch, 3 lks. wide, course S.60*W.; begin gradual ascent.</p> <p>Top of rise on W. slope of spur; begin descending.</p> <p>Intersected S. Bdy. of Sec. 36, 17 lks. W. of Cor. to Secs. 36 and 1, Tps. 30 and 31 S., R. 5 W.</p> <p>The post set for this Cor. is entirely gone, but all the bearing trees are standing. I restore this Cor. by setting a Laurel post, 4½ ft. long, 4 ins. sq., 24 ins. in the ground, marked T 31 S R 5 W S 1 on SW., T 30 S R 5 W S 36 on NW., faces with 6 notches on N., S., and W. edges, from which</p> <p>A Live Oak, 8 ins. diam., bears N.50*W., 7 lks. dist., marked T 30 S R 5 W S 36 B T.</p> <p>A Laurel, 10 ins. diam., bears S.83*W., 33 lks. dist., marked T 31 S R 5 W S 1 B T.</p> <p>These are the old bearing trees, which I re-mark, as the old marks are overgrown and quite dim.</p> <p>This Cor. stands in a thicket of Laurels, Firs and Live Oak.</p> <p>Land, mountainous.</p> <p>Soil, gravelly; 3rd rate.</p> <p>Timber, Fir, Laurel, Live Oak, Cedar and Pine.</p> <p>Undergrowth, mostly young Laurels and Firs.</p> <p style="text-align: right;">April 24th, 1889.</p>	-400 +80 -125
---	---	---------------------

Resurvey of
South Bdy. of T. 30 S., R. 4 W.

I, therefore begin at the Cor. to Tps. 30 and 31 S., Rs. 3 and 4 W., which is a Laurel post, 4 ins. sq., firmly set in the ground, marked T 30 S S 31 on NE.,