

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 30 S., R. 4 W.

CHAINS	
	<p>marked S 23 B T. The other trees are presumably washed away, as the river overflows this locality all winter. I restore this Cor. by setting a quartz rock, 32x8x6 ins. in a mound of stone (the nature of the ground, being a river bank not allowing to dig) marked with 2 notches on S. and 1 notch on E. edge, from which</p> <p>An Alder, 6 ins. diam., bears N.55*E., 78 lks. dist., marked T 30 S R 4 W S 25 B T.</p> <p>A Willow, 4 ins. diam., bears N.11$\frac{1}{2}$*E., 111 lks. dist., marked T 30 S R 4 W S 24 B T.</p> <p>An Alder, 8 ins. diam., bears S.38*W., 152 lks. dist., marked T 30 S R 4 W S 26 B T.</p> <p>A B. Oak, 24 ins. diam., bears N.53$\frac{1}{2}$*W., 287 lks. dist., marked T 30 S R 4 W S 23 B T.</p> <p>Thence I run South, on the true line bet. Secs. 25 and 26.</p> <p style="text-align: right;">Var. 19*15'E.</p> <p>Along river bar.</p>
2.00	To left bank of S. Umpqua River. Set flag on line South on the right bank, lay off base West. 1.50 chs.; flag bears S.30*9'E., making 2.58 chs. across.
4.58	Right bank of S. Umpqua River, course N.20*E.
5.00	Top of bank; enter bottom, level, with scattering Oak and Fir. +20
28.00	Enter river bar, overflowed all winter.
31.00	Right bank of S. Umpqua River, Set flag on line S. on left bank; thence run base E. 2 chs. Flag bears S.37*25'W., making 2.61 chs. across.
33.61	Left bank of river, course N.70*W.; enter timbered bottom 15 ft. above the level of the river,