

Subdivisions of T. 30 S., R. 4 W.

CHAINS		
	covered with Fir timber and thicket of Vine Maple and Hazel.	
40.00	Set a Cedar post, 3 ft. long, 3 ins. sq., 24 ins. in the ground, for $\frac{1}{4}$ Sec. Cor., marked $\frac{1}{4}$ S on W. face, from which A Fir, 15 ins. diam., bears S.23*W., 62 lks. dist., marked $\frac{1}{4}$ S B T. A Fir, 12 ins. diam., bears N. 17*E., 51 lks. dist., marked $\frac{1}{4}$ S B T.	
45.50	Begin ascent through Fir timber.	
59.00	Top of a sharp spur, course E. and W.; begin descent.	+700
61.00	A branch, 2 lks. wide, course W.; begin steep ascent.	-50
74.00	Pass from N. slope to E. slope of mountain, bears E. and W.	
80.00	Set a Laurel post, 4 ft. long, 4 ins. sq., 24 ins. in the ground, for Cor. to Secs. 25, 26, 35 and 36, marked T 30 S S 25 on NE., R 4 W S 36 on SE., S 35 on SW., S 26 on the NW. faces and 1 notch on S. and E. edges, from which A Fir, 24 ins. diam., bears N.54*E., 75 lks. dist., marked T 30 S R 4 W S 25 B T. A Fir, 12 ins. diam., bears S.53*E., 22 lks. dist., marked T 30 S R 4 W S 36 B T. A Fir, 6 ins. diam., bears S.46*W., 26 lks. dist., marked T 30 S R 4 W S 35 B T. A Fir, 16 ins. diam., bears N.64 $\frac{1}{2}$ *W., 37 lks. dist., marked T 30 S R 4 W S 26 B T.	+800
	Land, North-half, level; South-half, mountainous.	
	Soil, gravelly; N. half, 2nd rate, S. half, 3rd rate.	
	Timber, Fir, Oak, Cedar and Laurel.	
	Undergrowth, Vine Maple, Hazel and small Firs.	
	There is no trace of a survey having ever been done on this line, but few Oak trees are on the North half,	