

Subdivisions of T. 30 S., R. 4 W.

CHAINS	<p>but Firs are thick on the South half. But no surveyor's blaze to be found and the topography given in the field notes is at variance with the fact. Deputy Ford described a bottom from 19 chs. South of $\frac{1}{4}$ Sec. Cor. and running 1 ch. North of same to the river.</p>	
		May 2, 1889.
	<p>East, on a random line bet. Secs. 25 and 36.</p> <p style="text-align: right;">Var. 19°15'E.</p>	
37.59	<p>Intersected East Bdy. of Tp. 29, 37 chs. South of Cor. to Secs. 25, 36, 30 and 31, which is a Laurel post, 4 ins. sq., firmly set in the ground, marked T 30 S S 30 on the NE., R 3 W S 31 on the SE., R 4 W S 36 on the SW., S 25 on the NW. faces, with 5 notches on N. and 1 notch on S. edges, from which</p> <p style="padding-left: 40px;">A Fir, 30 ins. diam., bears N.30°E., 13 lks. dist., marked T 30 S R 3 W S 30 B T.</p> <p style="padding-left: 40px;">A Fir, 48 ins. diam., bears S.45°E., 30 lks. dist., marked T 30 S R 3 W S 31 B T.</p> <p style="padding-left: 40px;">A Fir, 20 ins. diam., bears S.41°W., 55 lks. dist., marked T 30 S R 4 W S 36 B T.</p> <p style="padding-left: 40px;">A Fir, 30 ins. diam., bears N.30°W., 13 lks. dist., marked T 30 S R 4 W S 25 B T.</p> <p>Thence S.52°W., on true line bet. Secs. 25 and 36.</p> <p style="text-align: right;">Var. 19°30'E.</p> <p>Ascending Umpqua mountain through Fir timber.</p>	
35.50	<p>Top of rise on a spur, course N.20°W., and S.20°E.</p> <p>Begin descent.</p>	+1200
38.00	<p>Canyon, course NW.; begin ascent.</p>	-100
47.70	<p>The Cor. to Secs. 25, 26, 35 and 36</p> <p>Land, mountainous.</p> <p>Soil, gravelly; 3rd rate.</p>	