

Subdivisions of T. 30 S., R. 4 W.

CHAINS

from which

A B. Oak, 24 ins. diam., bears S.35*E., 15 lks. dist.,
marked $\frac{1}{4}$ S B T.

A W. Oak, 15 ins. diam., bears N.55*E., 60 lks. dist.,
marked $\frac{1}{4}$ S B T.

At point of intersection, I set a Cedar post, $4\frac{1}{2}$ ft.

long, 4 ins. sq., 24 ins. in the ground, for closing
Cor. to Secs. 1 and 2, T. 30 S., R. 4 W., marked C C T
30 S S 1 on SE., R 4 W S 2 on SW. faces, and 6 notches
on S. and 1 on E. edges, from which

A B. Oak, 30 ins. diam., bears S.75*E., 43 lks.
dist., marked T 30 S R 4 W S 1 B T.

A W. Oak, 8 ins. diam., bears S.40 $3/4$ *W., 87 lks.
dist., marked T 30 S R 4 W S 2 B T.

Land, rolling,

Soil, gravelly loam; 2d rate.

Timber, Oak, Fir, Ash, Maple and Cedar.

Undergrowth, young Laurels, Oaks and Vine Maple.

The old $\frac{1}{4}$ Sec. Cor. could not be found, as the cultiva-
tion has destroyed all traces.

May 7, 1889.

I went to the locus of the Cor. of Secs. 22, 23, 26 and
27, but could not find any trace of a post or bearing
trees. W. H. Graham, who lives in Sec. 22 and who
accompanied me up here on my search for this Cor.,
informs me that he has repeatedly and thoroughly
searched for Cor. witness tree, or blazes on this line,
also for blazes on lines E. and W. of here, but
without success. I go therefore to the $\frac{1}{4}$ Sec. Cor.
bet. Secs. 22 and 23, and run
South, between Secs. 23 and 22.

Var. 19*10'E.