

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 30 S., R. 4 W.

CHAINS

A Laurel, 7 ins. diam., bears N. $6\frac{1}{2}^{\circ}$ W., 36 lks. dist., marked $\frac{1}{2}$ S B T.

(Note, the old post and bearing trees could not be found, as this locality has been burnt over, destroying all small trees.)

Keep descending.

Var. $19^{\circ}30'E$.

52.00	A canyon, course N.; begin ascent.	-400
57.00	Top of spur, course N. and S.; begin descent of W. slope of spur.	+100
68.50	Canyon, course N.; begin ascent.	-300
77.00	Top of spur, course N. and S.; begin descent.	+100
80.80	The Cor. to Secs. 10, 11, 14 and 15.	-60

Land, mountainous.

Soil, coarse gravel; 3rd rate.

Timber, Fir, Laurel and few Maple.

Undergrowth, young Firs, Laurels, Hazel and Greasewood.

May 10, 1889.

Var. $19^{\circ}30'E$.

North, on a random line bet. Secs. 10 and 11.

40.60	$\frac{1}{4}$ Sec. Cor. bears East, 4.15 chs.
79.24	Intersect North Bdy. of Sec. 10, 4.15 chs. W. of Cor. to Secs. 10, 11, 2 and 3. Post to this Cor., falling in a grain field, is gone, but the W. Oak, 30 ins. diam., marked S 11 B T, is standing. None of the other bearing trees or their stumps are remaining. I restore this Cor. by setting a Fir post, 4 ft. long, 4 ins. sq., 24 ins. in the ground, marked T 30 S S 2 on NE., R 4 W S 11 on SE., S 10 on SW., S 3 on NW. faces, with 5 notches on S., and 2 notches on E. edges, from which

A W. Oak, 30 ins. diam., bears S. 33° E., 380 lks. dist., marked T 30 S R 4 W S 11 B T.