

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 30 S., R. 4 W.

CHAINS		
14.50	Top of rise; begin descent, Oak openings.	+80
19.00	A gulch, course S.; begin ascent.	-50
23.50	Top of ascent; begin descent.	+75
26.50	Leave Oak openings; enter prairie.	
28.50	A gully, course S.; begin ascent.	-30
30.50	Top of spur, course N. and S.	-25.
38.25	<p>$\frac{1}{4}$ Sec. Cor. The post is gone, but I found a mound of stone in place, also the bearing tree in Sec. 15, marked $\frac{1}{4}$ S B T. I restore this Cor. by setting a basalt rock 14x10x6 ins., marked $\frac{1}{4}$ on N. face in a mound of stone, from which</p> <p>A B. Oak, 18 ins. diam., bears N.42*E., 155 lks. dist., marked $\frac{1}{4}$ S B T.</p> <p>This is the old bearing tree, which I re-mark.</p> <p>A boulder, 8x6 ft. and 3 ft. above the ground, bears S.22$\frac{1}{2}$*W., 107 lks. dist., marked x $\frac{1}{4}$ on N. face.</p> <p>Thence</p> <p>N.89*24'W., on true line bet. Secs. 15 and 22.</p> <p style="text-align: right;">Var. 19*25'E.</p> <p>A broken hilly prairie; ascend slightly.</p>	
6.00	A cliff, 35 ft. high, is N. A small pond is S.	
13.50	A perpendicular cliff, 20 ft. high, top of rise; begin descent.	+75
30.00	Enter Oak openings.	
37.50	Top of spur, course SW. and NE.; begin descent.	
39.25	<p>The Cor. to Secs. 15, 16, 21 and 22.</p> <p>Land, hilly.</p> <p>Soil, gravelly; 3rd rate.</p> <p>Timber, Oaks with a few Firs and Pine.</p> <p>Undergrowth, Greasewood and young Oaks.</p> <p style="text-align: right;">May 15, 1889.</p>	
	Var. 19*35'E.	
	North, on random line bet. Secs. 15 and 16.	
40.00	Set temp. post.	
78.57	<p>Intersected North Bdy. of Sec. 16, 122 lks. W. of Cor. to Secs. 9, 10, 15 and 16. The post and the only bearing</p>	