

Subdivisions of T. 30 S., R. 4 W.

CHAINS
39.69

$\frac{1}{4}$ Sec. Cor. post of this corner is gone, but both bearing trees are standing. I restore this corner by setting a Fir post, 3 ft. long, 3 ins. sq., 24 ins. in the ground, marked $\frac{1}{4}$ S on W. face, from which
A W. Oak, 40 ins. diam., bears S.7°E., 537 lks. dist., marked $\frac{1}{4}$ S B T.

This is the old bearing tree, whose marks I renew. The other bearing tree I find to bear S. 5°E and not S.85°W., as given in the field notes. I mark A B. Oak, 15 ins. diam., S.13°W., 506 lks. dist., marked $\frac{1}{4}$ S B T.

Thence

S.47°W., on true line between Secs. 9 and 10.

Var. 18°40'E.

- 0.50 Leave grain field; enter pasture.
- 5.00 Leave prairie; enter Oak openings.
- 12.50 Raymond's house, bears West.
- 17.00 Leave enclosure. County road to Canyonville, course West; descend sharply.
- 21.00 Day's Creek bank, 30 ft. deep, course W. 20 lks. wide.
- 24.00 Schoolhouse, bears West.
- 27.00 Leave Oak openings; enter garden.
- 33.75 Leave garden.
- 34.81 Right back of S. Umpqua, course N.20°W., thence by traverse S.32 $\frac{1}{2}$ °E., 5.19 chs., giving a Southing of 4.38 chs., and Easting 2.77 chs.
- 39.19 The Cor. of Secs. 9, 10, 15 and 16.

Land, rolling.

Soil, gravelly, loam, 2d rate.

Timber, Oak, Fir, Pine, Laurel and Alder.

Undergrowth, young Oaks and Laurels.

May 17, 1889.

Var. 18°50'E.

East, on a random line between Secs. 3 and 10.