

Subdivisions of T. 30 S., R. 4 W.

CHAINS		Var. 18°50'E.	
	North, on a random line between Secs. 3 and 4.		
39.08	<p>¼ Sec. Cor. bears E. 70 lks. The post for this corner is gone. I find a B. Oak marked ¼ S B T. Taking this to be called an Alder in the field notes of original survey, (no other bearing trees could be found, and no Alders anywhere,) I restored this corner by setting a Laurel post 3 ft. long, 3 ins. sq., 24 ins. in the ground, marked ¼ S on W. face, from which</p> <p>A B. Oak, 24 ins. diam., bears S.45°W., 26 lks. dist., marked ¼ S B T.</p> <p>This had been marked, but I renew the marks, the same being dim.</p> <p>A W. Oak, 6 ins. diam., bears N. 34½°E., 83 lks. dist., marked ¼ S B T.</p> <p>Thence</p> <p>S. 1°W., on true line between Secs. 3 and 4.</p>	Var. 19°5'E.	
	Along E. slope through Oak openings.		
13.00	Top of spur, course S.10°E., and N.10°W. Begin descent on West slope.		
21.00	Top of spur, course SE. and NW; still descending.		
39.08	<p>The Cor., to Secs. 3, 4, 9 and 10.</p> <p>I return to the ¼ Sec. Cor. and run thence</p> <p>North, on true line between Secs. 3 and 4.</p>	Var. 19°5'E.	
	Ascend through thick underbrush.		
11.00	<p>Top of ridge, course S.80°W., and N.80°E.</p> <p>Begin descent through Fir timber.</p>		+200
		Var. 19°30'E.	
20.50	A gulch, course NE.; descend along E. slope.		-150
25.00		Var. 18°40'E.	
34.00	Gulch, course E.		
40.50	A gulch, course E.; begin ascent.		-200