

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 30 S., R. 4 W.

CHAINS	<p>Land, hilly.                  Soil, gravelly, 3d rate.                  Timber, Fir, Oak, Laurel, Maple and Ash.                  Undergrowth, Vine Maple, Hazel, young Firs, Oaks and Laurels.</p>	
	Var. 19*5'E.	
	East, on a random line between Secs. 21 and 28	
40.92	$\frac{1}{4}$ Sec. bears S. 192 lks.	
79.25	Intersect N. and S. line 259 lks. N. of Cor., to Secs. 21, 28, 22 and 27.	
	Thence	
	N.89*W., on true line between Secs. 21 and 28.	
	Var. 19*15'E	
	Descend through Fir timber.	
13.00	Foot of hill; enter bottom, bears SW. and NE.	-50
17.40	A branch, 10 lks. wide, course NE.	
20.00	A wagon road, course SW. and NE; leave bottom; begin ascent of a brushy hill.	
24.00	Leave big Fir timber.	
32.40	Leave underbrush; enter Oak openings.	
33.40	Top of ascent; begin descent.	+120
36.40	A canyon, course S., very brushy and steep.	-90
38.33	<p><math>\frac{1}{4}</math> Sec. Cor. post is gone, but both bearing trees are standing; I restore this corner, by setting an Oak post 3 ft. long, 3 ins. sq., 24 ins. in the ground, marked <math>\frac{1}{4}</math> S on N. face, from which</p> <p style="padding-left: 2em;">A W. Oak, 16 ins. diam., bears N.85*E., 400 lks. dist., marked <math>\frac{1}{4}</math> S B T.</p> <p style="padding-left: 2em;">A B. Oak, 10 ins. diam., bears S.55*E., 325 lks. dist., marked <math>\frac{1}{4}</math> S B T.</p> <p>These are the old bearing trees, whose marks, being dim, I renew.</p>	+70