

Subdivisions of T. 30 S., R. 4 W.

CHAINS		
	Thence	
	N.87*20'W., on true line between Secs. 21 and 28.	
	Var. 19*5'E.	
1.50	Enter prairie and enclosure; begin descent of S. slope of hill.	
12.00	A branch, course S., 1 lk. wide; begin ascent of SE. slope.	-120
24.00	Top of spur, course N. and S.; begin descent.	+150
35.50	A gulch, course S.; begin ascent; scattering Oak.	-90
40.92	The Cor. to Secs. 20, 21, 28 and 29.	
	Land, hilly.	
	Soil, gravelly, 3d rate.	
	Timber, Oak, Fir, Laurel and Cedar.	
	Undergrowth, mostly young Oaks, Fir, Laurel, Hazel and Vine Maple.	
	Var. 19*5'E.	
	North, on a random line between Secs. 20 and 21.	
38.90	$\frac{1}{4}$ Sec. Cor. bears E. 93 lks.	
79.10	Intersect N. Bdy. of Sec. 20, 178 lks. West of Cor. to Secs. 16, 17, 20 and 21. The post set for this corner is gone; all the bearing trees but the B. Oak in Sec. 17 have been destroyed by fire a long time ago, but this B. Oak shows yet B.T., also partly burnt. I restore this corner by setting a Fir post, 4 ft. long, $4\frac{1}{2}$ ins. sq., 24 ins. in the ground, marked T 30 S S 16 on NE., R 4 W S 21 on SE., S 20 on SW., S 17 on NW. faces with 3 notches on S., and 4 notches on E edges, from which	
	A B, Oak, 16 ins. diam., bears N.60*W., 13 lks. dist., marked T 30 S R 4 W S 17 B T.	
	This is the old bearing tree, which I remark.	
	A Fir, 14 ins. diam., bears N.20*E., 10 lks. dist., marked T 30 S R 4 W S 16 B T.	
	A Fir, 18 ins. diam., bears S.47 $\frac{1}{2}$ *E., 19 lks. dist., marked T 30 S R 4 W S 21 B T.	