

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 30 S., R. 4 W.

CHAINS

A B. Oak, 6 ins. diam., bears S.73*W., 11 lks. dist.,
marked T 30 S R 4 W S 20 B T.

Thence

S.1*13'W., on true line between Secs. 20 and 21.

Var. 19*5'E.

Ascending through small Firs and Laurels which are 60. ft.
high and about 8 ins. diam.

15.00 Leave Laurels; enter brushy Fir timber.

30.50 Top of ridge, course SW. and E.; enter Oak openings;
begin descent.

Var. 19*39'E.

40.20 $\frac{1}{4}$ Sec. Cor. The old post is gone, but both the bearing
trees are standing; I restore this corner by setting
an Oak post 3 ft. long, 3 ins. sq., 24 ins. in the
ground,, marked $\frac{1}{4}$ S on W. face; also set a basalt rock
14x8x6 ins. along side, from which

A B. Oak, 30 ins. diam., bears S.70*E., 260 lks.
dist., marked $\frac{1}{4}$ S B T.

A W. Oak, 15 ins. diam., bears N.10*W., 370 lks.
dist., marked $\frac{1}{4}$ S. B T.

Both are the old bearing trees, which, as the old
marks are dim, I remark.

Thence

S.1*22'W., on true line between Secs. 20 and 21.

Descending S. hill slope; prairie, covered with scatter-
ing Oaks.

38.90 The Cor. to Secs. ~~16~~, ~~17~~, 20 and 21, ~~28-29~~.
Land, hilly.

Soil, gravelly, S. half, 2d rate, N. half, 3d rate.

Timber, Oak, Fir and Laurel.

Undergrowth, young Oaks, Firs and Laurels.

May 20, 1889.

Var. 19*5'E.

East, on a random line between Secs. 16 and 21.

40.00 Set temp. $\frac{1}{4}$ Sec. Cor.

80.74 Intersect N. and S. line, 303 lks. N. of Cor. to Secs.

+250