

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 30 S., R. 4 W.

CHAINS	<p>Land, E. quarter rolling, W. three quarters mountainous. Soil, gravelly E. quarter, 2d rate, W. three quarters, 3d rate. Timber, Fir, Oak, Laurel and Pine. Undergrowth, young Fir, Oaks, Laurels and Pines.</p>
37.70	<p style="text-align: right;">Var. 19*5'E.</p> <p>North, on a random line between Secs. 16 and 17. ½ Sec. Cor. bears E. 67 lks.</p>
76.53	<p>Intersect N. Bdy. of Sec. 17, 135 lks. W. of Cor. to Secs. 8, 9, 16 and 17. The post set for this corner is gone, the only bearing tree has been cut down, but the log still shows survey or marks. I am informed that this has been the original bearing tree. It is the stump of a W. Oak, 18 ins. diam.; the marks showing it to have stood in Sec. 17. I restore this corner by setting a basalt rock 10x8x7 ins., 7 ins. in the ground; marked with 4 notches on S. and E. edges; raised a mound of stone along side, from which A W. Oak, 15 ins. diam., bears S.55*E., 384 lks. dist., marked T. 30 S R 4 W S 16 B T. A W. Oak, 6 ins. diam., bears S.5 3/4*W., 272 lks. dist., marked T. 30 S R 4 W S 17 B T. No trees in Sec. 8 and 9, within 20 chs. The position of this corner was afterwards verified by running from the interior corner of Donation Land Claim No. 44, N. 20 chs. and E. 20 chs., agreeing with field notes of survey of said claim,</p>
	<p>Thence S.1*W., on true line between Secs. 16 and 17.</p>
2.00	<p style="text-align: right;">Var. 19*E.</p> <p>Through a cornfield. Leave cornfield; begin ascent, through Oak openings, with young Oaks.</p>
15.00	<p>A gulch and dug ditch, course NE.</p>
18.50	<p>Leave Oak timber, enter Fir timber, ascent steeper.</p>