

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 30 S., R. 4 W.

CHAINS 32.00	Top of spur, course NW. and SE.; leave Firs, enter Oak openings; begin to descend.	250
35.50	Foot of descent; begin ascent of W. slope.	60
38.83	<p>1/4 Sec. Cor. The post set for this corner is gone, but both witness trees are standing. I restore this corner by setting a W. Oak post, 3 ft. long, 3 ins. sq., 24 ins. in the ground, marked 1/4 S. on W. face, from which</p> <p>A B. Oak, 10 ins. diam., bears N.52*W., 138 lks. dist., marked 1/4 S B T.</p> <p>A B. Oak, 10 ins. diam., bears S.25*E., 265 lks. dist., marked 1/4 S B T.</p> <p>These are the old bearing trees, whose marks being dim, I renew.</p> <p>Thence</p> <p>S. 1*W.</p> <p style="text-align: right;">Var. 19*12'E.</p> <p>J. Weaver's house bears S.81*W.</p> <p>Clough's barn bears N.77*W.</p> <p>Chapman's house bears N.68 3/4*W.</p> <p>P. Weaver's house bears N.67 1/4*W.</p> <p>Along W. slope of hill through Oak timber.</p>	
1.50	begin descent.	
14.50	Foot of descent. Leave Oak timber, enter Fir timber; begin to ascend.	
25.00	Very steep ascent.	
33.50		Var. 18*50'E.
37.70	<p>The Cor. to Secs. 16, 17, 20 and 21.</p> <p>Land, N. half, hilly; S. half, mountainous.</p> <p>Soil, gravelly, N. half 2d rate, S half, 3d rate.</p> <p>Timber, Fir, Oak and Laurel.</p> <p>Undergrowth, Hazel, young Oaks, Fir and Laurel.</p> <p style="text-align: right;">May 21, 1889.</p>	
		Var. 19*E.
	East, on a random line between Secs. 16 and 9.	
40.00	Set temp. post.	
80.24	Intersect N. and S. line 106 chs. N. of corner, to	