

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T 30 S., R 4 W.

CHAINS

No other tree S. of line.

Var. 18*10'E.

Level prairie, grainfield.

No pits dug or mound raised on account of cultivation.

80.92 The Cor. to Secs. 7, 8, 17 and 18.

Land, W.20 chs., hilly; E. 60 chs., level.

Soil, W. quarter, gravelly; E. three quarters, loam,
mixed with gravel.

Timber, Oaks and Alder.

Var. 18*55'E.

North, on a random line between Secs. 7 and 8.

Through level prairie, grainfield.

39.58 $\frac{1}{2}$ Sec. Cor.

78.54 Intersect North Bdy. of Sec. 7, 111 lks. West of Cor.
to Sec. 5, 6, 7 and 8.

The post set for this corner is gone, but three bearing
trees are standing. I restore by setting an Oak post
4 ft. long, 4 ins. square, 24 ins. in the ground,
marked T 30 S S 5 on NE., R 4 W S 8 on SE., S 7 on SW.,
and S 6 on NW. faces, with 5 notches on S. and E. edges,
from which

A B.Oak, 20 ins. diam., bears N.65*E., 60 lks. dist.,
marked T 30 S R 4 W S 5 B T.

A B. Oak, 10 ins. diam., bears S.55* E., 85 lks.
dist., marked T 30 S R 4 W S 8 B T.

A B. Oak, 16 ins. diam., bears N.15*W., 295 lks.
dist., marked T 30 S R 4 W S 6 B T.

These are the original bearing trees, which I re-
mark, the old marks being overgrown; also

A W. Oak, 20 ins. diam., bears N.88*W., 60 lks.
dist., instead of S.88*W., as described in the
field notes furnished me, this tree standing
Sec. 6, already supplied. I mark a laurel 6 ins.
in diam., bears S 52 $\frac{1}{2}$ *W., 33 lks. dist., marked