

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T 30 S., R 4 W.

CHAINS		
40.00	Set temporary $\frac{1}{2}$ Sec. post.	
81.25	Intersect N. and S. line 80 lks. North of Cor. to	
	Sec. 4, 5, 8 and 9.	
	Thence	
	N. 89° 26' W., on true line between Secs. 5 and 8.	
	Var. 17° 40' E.	
	Ascend E. slope, through oak openings with pine underbrush	
6.00	Top of spur, begin steep descent.	+40
19.85	A branch, 10 lks. wide, course S.	-300
20.50	Enter prairie, nearly level.	
24.50	Enter heavy underbrush, begin to ascend.	
	Var. 19° 22' E.	
40.62	Set a Fir post, 3 ft. long, 3 ins. square, 24 ins. in	+300
	the ground for $\frac{1}{4}$ Sec. Cor., marked $\frac{1}{4}$ S on N. face,	
	from which	
	A Laurel, 4 ins. diam., bears N. 38 $\frac{3}{4}$ ° E., 25 lks. dist., marked $\frac{1}{4}$ S B T.	
	A Laurel, 6 ins. diam., bears S. 6 $\frac{1}{2}$ ° W., 19 lks. dist., marked $\frac{1}{4}$ S B T.	
	The old post, nor the old bearing trees could not be found. This is a locality which has been burned over, but I think there is some mistake in the field notes, as there are no oak trees growing here.	
	Var. 18° 55' E.	
	Ascending through heavy underbrush.	
47.00	Enter oak openings, bear N. and S.	
48.30	Enter enclosure.	
50.50	Top of ridge, course N. and S., begin descent of W. hill-	+75
	side.	
	Var. 19° 30' E.	
58.50	Foot of descent, begin ascent of S. hillside.	
64.50		Var. 18° 40' E.
81.25	The Cor. to Secs. 5, 6, 7 and 8.	+50

SEE CS. 51/85  
LYTEL LETTER 7/60