

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T 30 S., R 4 W.

CHAINS 31.00	Top of ridge, course N. and S., begin descent S. slope of hill.	
		Var. 20*5'E.
39.48	The Cor. to Secs. 5, 6, 7 and 8. Land, mountainous. Soil, gravelly, 3d rate. Timber, Fir, Pine, Oak, Laurel and Maple. Undergrowth, young fir, oaks and laurels.	-60
		June 1, 1889.
		Var. 19*35'E.
	North, on a random line between Secs. 5 and 6.	
39.65	$\frac{1}{2}$ Sec. Cor. bears East 66 lks. The post for this corner is gone, but both bearing trees are standing. I restore this corner by setting a Fir post, 3 ft. long, 3 ins. square, 24 ins. in the ground, marked $\frac{1}{4}$ S on W. face, from which A Laurel, 36 ins. diam., bears N.75*W., 24 lks. dist., marked $\frac{1}{4}$ S B T. A B. Oak, 12 ins. diam., bears N.45*E., 97 lks. dist., marked $\frac{1}{4}$ S B T. These are the old bearing trees, whose marks being overgrown and dim, I renew.	
	Thence S.57' W., on true line between Secs. 5 and 6.	
		Var. 21*5'E.
	Descend through heavy underbrush.	-50
13.00	Wire fence, bears E. and W., begin ascent.	
24.50	Top of ridge, course E. and W., descend SE. slope.	+150
36.50	Begin ascent.	-75
39.65	The Cor., to Secs. 5, 6, 7 and 8. I return to the $\frac{1}{2}$ Sec. Cor., thence I run North, on true line between Secs. 6 and 5.	
		Var. 21*5'E.
	Ascend, through oak timber and heavy underbrush.	