

# County Surveyor's Record, Douglas County, Oregon

7117

## Subdivisions of T. 30 S., R. 4 W.

CHAINS		
	Huckleberry and logs. 40 chs.	
	Var. 19*E.	
	S.88*08'E., on a random line between Secs. 28 and 33.	
40.00	Set temp. $\frac{1}{4}$ Sec. Cor.	
79.32	Intersect N. and S. line, 18 lks. North of the Cor. to Secs. 27, 28, 33 and 34. Thence I run N.88*W., on a true line between Secs. 28 and 33	
	Var. 19*E.	
	Descend.	-150
13.05	A stream, 3 lks. wide, course NW. Ascend.	+10
13.60	Descend.	-15
14.68	A stream, 8 lks. wide, course North.	
28.70	A Fir, 36 ins. diam., on line marked with 2 notches on E. and W. sides. <span style="float: right;">Oct 14, 1893.</span>	
39.66	Set a Fir post, 4 ft. long, 4 ins. square, 24 ins. in the ground for $\frac{1}{4}$ Sec. Cor., marked $\frac{1}{4}$ S on N. face; from which A Laurel, 12 ins. diam., bears S.37 $\frac{1}{2}$ *W., 28 lks. dist., marked $\frac{1}{4}$ S B T. A Fir, 10 ins. diam., bears N.3 $\frac{1}{4}$ *W., 44 $\frac{1}{2}$ lks. dist., marked $\frac{1}{4}$ S B T.	
41.75	A ravine, course, N. and S. Descend.	-40
47.50	Top of ridge, course N. and S.	
50.35	A Fir, 5 ft. diam., on line marked with 2 notches on E. and W. sides.	
67.08	A stream, 3 lks. wide, course N.80*W., Ascend.	+50
75.50	Descend.	-15
79.32	The Cor. to Secs. 28, 29, 32 and 33. Land, mountainous. 79.32 chs. Soil, 3d rate. Timber, heavy Fir, Laurel and Maple. 79.32 chs. Undergrowth, dense with Vine-maple, Laurel, Arrow-wood, Fir and Hazel. 79.32 chs.	