

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 30 S., R. 5 W.

CHAINS	<p>First $\frac{1}{2}$ mile, first rate soil, last $\frac{1}{2}$, second rate, rolling land.</p> <p>Timber, oak, pine & fir.</p> <p>Underbrush, oak & laurel.</p>	
<p>40.00</p> <p>79.78</p> <p>27.00</p> <p>32.00</p> <p>39.89</p> <p>41.50</p> <p>55.00</p> <p>60.30</p> <p>64.00</p> <p>65.00</p> <p>75.00</p> <p>79.78</p>	<p style="text-align: right;">Va. 18*10'E.</p> <p>East, on random between Secs. 13 & 24.</p> <p>Set temporary $\frac{1}{2}$ sec. post.</p> <p>Intersect, East boundary 58 lks. South of Sec. cor. S.89*35'W, on ture line between Secs. 13 & 24.</p> <p>House, N.15*E.</p> <p>Left Bank of South Umpqua, course S.45*W</p> <p>Chained across river.</p> <p>Right Bank of River.</p> <p>Set $\frac{1}{2}$ sec. post at average distance, from which,</p> <p style="padding-left: 40px;">A Balm, 20 ins. diam., bears N.80*E. 482 lks. dist.</p> <p style="padding-left: 40px;">A cedar, 8 ins. diam., bears S.7*E. 370 lks. dist.</p> <p>Elijah Morgan's house N,65*W.</p> <p>Entered Morgan's field.</p> <p>Left field. Began to ascend hill, bears SW & NE.</p> <p>A pine 40 ins. diam.</p> <p>Top of hill bears S.23*E & N.20*W.</p> <p>Began to descend hill.</p> <p>A small stream 8 lks. wide course S.10*E. E. Morgan's House N.73*E.</p> <p>To Sec. cor.</p> <p>Second rate, soil.</p> <p>Last half mile rolling land.</p> <p>Timber, Oak, fir & pine.</p> <p>Undergrowth, oak.</p>	<p>level</p> <p>-20</p> <p>+20</p> <p>-75</p> <p>+20</p>
<p>40.00</p>	<p style="text-align: right;">Va. 18$\frac{1}{2}$*E.</p> <p>North, between Secs. 13 & 14.</p> <p>Set $\frac{1}{2}$ sec. post from which,</p> <p style="padding-left: 40px;">A laurel, 15 ins. diam., bears N.53*E. 40 lks. dist.</p> <p style="padding-left: 40px;">A laurel, 12 ins. diam., bears N.35*W. 46 lks. dist.</p>	<p>+100</p>