



Re-survey of exterior lines of T. 31 S. R. 5 W.

CHAINS	<u>North bdy.</u>
	<p>side and from which,</p> <p style="padding-left: 40px;">A laurel, 14 ins. diam., bears N.15*W, 25 lks. dist. marked $\frac{1}{4}$ S B T.</p> <p style="padding-left: 40px;">A laurel, 12 ins. diam., bears S.10*E, 30 lks. dist. marked $\frac{1}{4}$ S B T.</p>
73.00	Top of ridge, course NW & SE.
80.00	<p>Set a maple post 4 ft. long, 4 ins. sq., 20 ins. in the ground for the corner to sec. 1, 2, 35 & 36. marked, T 30 S R 5 W S 36 on the NE face, T 31 S S 1 on the SE face, S 2 on the SW faces, and S 35 on the NW face, also one notch on the East and five notches on the W. angles of the same, and from which,</p> <p style="padding-left: 40px;">A fir, 14 ins. diam., bears N.40*E, 26 lks. dist. marked T 30 S R 5 W S 36 B T.</p> <p style="padding-left: 40px;">A maple 12 ins. diam., bears S.40*E, 29 lks. dist. marked T 31 S R 5 W S 1 B T.</p> <p style="padding-left: 40px;">A fir, 24 ins. diam., bears S.20*W, 56 lks. dist. marked T 31 S R 5 W S 2 B T.</p> <p style="padding-left: 40px;">A dogwood, 6 ins. diam., bears N.28*W, 15 lks. dist. marked T 30 S R 5 W S 35 B T.</p> <p>Land, steep mountainous, rocky and broken.</p> <p>Soil, 4th. rate.</p> <p>Timber, fir, laurel, cedar & maple.</p> <p>Thick undergrowth of fir, laurel, cedar, maple, live oak, hazel and balm.</p>
	<p>S, 89*38'E, on a true line between Secs. 1 & 36.</p> <p style="padding-left: 80px;">Va. 19*E.</p>
	Steep descent.
27.00	A creek 2 lks. wide course North, steep ascent.
38.00	Top of spur course N. steep descent.
40.00	<p>Set a stone 16x12x6 ins. for the $\frac{1}{4}$ sec. corner, marked $\frac{1}{4}$ on the N side and, from which,</p> <p style="padding-left: 40px;">A fir, 26 ins. diam., bears S.30*E, 50 lks. dist. marked $\frac{1}{4}$ S B T.</p>