

## County Surveyor's Record, Douglas County, Oregon

## Re-survey of Exterior lines of T. 31 S., R 5 W.

CHAINS

North bdy.

A laurel, 6 ins. diam., bears N.55°W, 21 lks. dist.  
marked  $\frac{1}{2}$  S B T.

67.00 A creek, 20 lks. wide course NW. Steep ascent.

80.00 To the corner to T. 30 & 31 S., Rs. 4 & 5 W.

Land, very mountainous and broken.

Soil, rocky, 4th. rate.

Timber, dense forest of fir, cedar and laurel.

Thick undergrowth of fir, cedar & laurel, with maple,  
live-oak and hazel.

August 22, 1882.

## General Description.

This township is generally mountainous, excepting narrow bottom along the creeks. It is densely covered with forests chiefly, fir, also pine, cedar, laurel, yew, hemlock, etc. Thick undergrowth, chiefly laurel, also same kind of wood as large timber with hazel, dogwood, maple, live-oak & balm.

There are six or eight settlements made in the township and as the timbers are very valuable it should be surveyed.

Subdivisions of T. 30 S., R. 5 W. As surveyed by Oscar F. Thiel U. S. Deputy Surveyor, under his contract, No. 658, dated May 21, 1896.

I begin at the cor. of secs. 11, 12, 13 and 14, which is a fir post 5 ins. sq. which had fallen to the ground and which I reset 24 ins. in the ground, which post was marked and witnessed as described by the surveyor general.

Thence I run,

N.0°1'W, bet. secs. 11 and 12.

Steep descent, through heavy fir timber and dense undergrowth of vine maple and hazel, of a NE slope of spur, bears SE and NW.