

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 30 S., R. 5 W.

CHAINS

marked $\frac{1}{4}$ S B T.

Keep ascending a N. slope through small fir timber.

55.20 Top of dividing ridge, bears E and W., 350 ft. above $\frac{1}{4}$ sec. cor.

57.70 A dim wagon road, bears E. and W.

60.50 A wire fence, bears NE and SW., enter mixed oak and fir timber.

Begin descent of S. slope of mountain.

63.25 Leave fir timber, descend through oak timber, bears E and W.

69.75 Change to descent of W. slope.

75.75 Top of spur, bears NE and SW., descend spur.

83.25 To cor. of secs. 2, 3, 10 & 11, 250 ft. below top of dividing ridge.

Land, mountainous.

Soil, gravelly and stoney, 3rd. rate.

Timber, fir, oak, pine & laurel.

Dense undergrowth of small black oaks, firs, hazel and arrow-root.

Mountainous, or heavily timbered land. 83.25 chs. and 5.65 chs. closing line.

July 21, 1896

Not being able to find the cor. of secs. 9, 10, 15 & 16, or the witness trees belonging to the same, as the fire has destroyed the timber in the supposed locus of this cor. I go to the $\frac{1}{4}$ sec. cor. bet. secs. 15 and 16, which is a post, 3 ins. sq. 24 ins. high, marked and witnessed as described by the surveyor general, and run North bet. secs. 15 and 16.

40.00 Set temp. sec. cor.

I could not find any sign of a line, in the neighborhood of this cor., running E. or W., so I returned to the cor. of secs. 10, 11, 14 & 15.

At the cor. of secs. 10, 11, 14 & 15.