

Subdivisions of T. 30 S., R. 5 W.

CHAINS

From $\frac{1}{4}$ sec. cor. bet. secs. 4 & 5.

I run South.

9.71 A post, marked by County Surveyor, standing in junction of fences, bears West 45 lks.

14.25 Top of spur, begin descent.

40.38 Intersect E & W line, 70 lks. E. of sec. cor. to secs. 4, 5, 8 & 9.

Land, N $\frac{1}{2}$ level, S $\frac{1}{2}$ hilly.

Soil, N $\frac{1}{2}$ loam, S $\frac{1}{2}$ gravelly; 1st. and 3rd. rate.

Timber, oak on S $\frac{1}{2}$.

Remeasurement of resurvey of North bdy. of T. 30 S. R. 5 W.

Begin at cor. to secs. 4 & 5, T. 30 S., R. 5 W., and secs. 32 & 33 T. 29 S., R. 5 W., as noted.

Thence I run.

N.89*42'E, on line bet. secs. 4 & 33.

Through level prairie.

14.70 Cor. of fences, bears E & N & S.

38.65 Junction of 4 fences, begin ascent and enter oak timber.

I made a careful search in this vicinity for the $\frac{1}{4}$ Sec. cor., but could not find any trace of cor. post or witness trees, some stumps are left West of this point.

At the supposed $\frac{1}{4}$ sec. cor. bet. secs. 4 & 33.

58.95 Cor. of fences, bears N & W.

69.45 The cor. to secs. 33 & 34.

76.40 The closing cor. to secs. 3 & 4.

Land, W $\frac{1}{2}$ level, E $\frac{1}{2}$ hilly.

Soil, W $\frac{1}{2}$ loam, E $\frac{1}{2}$ gravelly, 1st. and 3rd. rate.

Timber, on E $\frac{1}{2}$ oak, laurel & fir.

N.89*42'E, along N. bdy. of sec. 3.

Descend through dense undergrowth of oaks, laurels, small firs.