

Subdivisions of T. 30 S., R. 5 W.

CHAINS

N.89°42'E, along North, bdy of sec. 1.

At the closing cor. of secs. 1 and 2.

Keep ascending.

- 4.25 Top of dividing ridge, bears NE & SW, 150 ft. above closing corner.
 - 4.75 Enter fir timber, bears N and S.
 - 8.25 Enter oak timber, bears NE and SW.
 - 9.00 Begin descent.
 - 34.56 The $\frac{1}{2}$ sec. cor. bet. secs. 36 and 1, a fir post, 2 ft. above ground, 3 ins. sq. marked and witnessed as described by the surveyor general.
- 34.56 + 79.44 + 5.65 chs. equals 119.65 chs. as the distance from cor. of secs 34 and 35 to the $\frac{1}{2}$ sec. cor. bet. secs. 36 and 1, $\frac{1}{3}$ there of is 39.88 deducting therefrom 34.56 leaves 5.32, W. of the temp. post as the proper place, I set a basalt stone 7x8x9, 6 ins. in the ground for cor. of secs. 35 and 36. T. 29 S., R. 5 W., marked with 1 groove on the E., and 5 grooves on the W. faces, and raised a mound of stone, 2 ft. base, 1 $\frac{1}{2}$ ft. high N. of cor. No trees within limits.

July 29, 1896.

GENERAL DESCRIPTION

The most of the area of this surveyed land is comprised in a basin, watered by Mill creek and surrounded by a high mountain ridge all around, and which through its numerous spurs fills up the entire interior. It is well watered by small streamlets and several springs, but contains no arable land to speak of, probably not more than $\frac{1}{2}$ to 1 acre near each of its 3 houses, but none to make any hay. There is no one living at either house, nor is there any indication of a permanent residence. If one man owned the whole of this basin, he might derive a small benefit by the

35/36