

Retracements of Subdivisional lines of T. 30 S., R. 5 W.

CHAINS	
	<p>begin descent.</p>
79.05	<p>Intersect E. bdy. of T. 3.47 chs. S. of cor. of secs. 12, 13, 7 &amp; 18, which is a pine post, 2 ft. high, 4 ins. sq., marked and witnessed as described by the surveyor general.</p> <p>Land, mountainous.</p> <p>Soil, gravelly; 4th rate.</p> <p>Timber, fir, oak, cedar, laurel, pine.</p> <p>Mountainous, land. 79.05 chs.</p> <p style="text-align: right;">April 29, 1897</p>
	<p>N.89°42'E, on North bdy. of sec. 1.</p> <p>Ascend mountain slope, covered by heavy fir timber, and dense undergrowth of hazels.</p>
20.50	<p>Top of ridge, bears N &amp; S. 140 ft. above <math>\frac{1}{4}</math> sec. cor. begin descent of</p>
33.15	<p>A branch 3 lks. wide, course SE, 200 ft. below top of ridge, begin ascent.</p>
36.50	<p>Top of spur, bears S. and N. 60 ft. above branch, began descent.</p>
44.55	<p>The cor. of T. 29 and 30 S., Rs. 4 and 5 W., which is a cedar post 2<math>\frac{1}{2}</math> ft. above ground, 4 ins. sq., marked and witnessed as described by the surveyor general.</p> <p>Land, mountainous.</p> <p>Soil, gravelly, 4th. rate.</p> <p>Timber, fir, oak, pine, laurel.</p> <p>Mountainous or heavily timbered land, 44.55 chs.</p> <p style="text-align: right;">April 30, 1897.</p>
	<p>At the cor. of secs. 9, 10, 15 &amp; 16.</p> <p>S.89°45'W, on line bet. secs. 9 and 16.</p> <p>Moderate ascent of mountain slope, covered by oak, fir, laurel and pines.</p>
10.00	<p>Top of spur, bears N and S., 140 ft. above sec. cor. begin descent of W. slope.</p>
40.00	<p>No trace of the <math>\frac{1}{4}</math> sec. cor. or its bearing trees to be</p>