

Subdivisions of T. 30 S., R. 7 W., W. M.

CHAINS

	S0*21'E. on a true line between secs. 1 and 2.	
28.25	Leave timber., Enter plowed field.	
33.22	Set $\frac{1}{4}$ sec. post from which	-185
	A Pine, 12 ins. diam., bears N.48*E., 283 lks. dist.	
	An Alder, 8 ins. diam., bears S.50*W., 254 lks. dist.	
42.00	A small creek, course SW.	
65.22	A small creek, 8 lks. wide, course W.	-200
69.22	Leave field.	
73.22	The sec. cor.	-100
	Land good, 2nd. rate. 1st. rate along creek bottoms.	
	Timber, pine, fir, cedar, laurel, oak and a few other species, 1st. rate.	
	May 17, 1872.	
	North, between secs. 34 and 35.	
	Va. 22*E.	
20.00	Enter flat bench spring, course NW.	-300
40.00	Set $\frac{1}{4}$ sec. post from which	
	A pine, 14 ins. diam., bears N.85*E., 75 lks. dist.	
	A pine, 24 ins. diam., bears S.86*W., 125 lks. dist.	
45.50	A marshy spring, course W.	
56.34	Cow creek, 75 lks. wide, course E.	-350
72.00	Begin ascent.	
80.00	Set post cor. to secs. 26, 27, 34 and 35 from which	+100
	A live oak, 12 ins. diam., bears N.72*E., 76 lks. dist.	
	A laurel, 10 ins. diam., bears S.50*E., 142 lks. dist.	
	A live oak, 16 ins. diam., bears S.50*W., 35 lks. dist.	
	A fir, 12 ins. diam., bears N.75*W., 23 lks. dist.	
	Land, S. of creek good, first rate grass land. N. of creek, rocky, broken, 3rd rate, but little timber.	
	East, on a random line between secs. 26 and 35.	
	Va. 19*E.	
40.00	Set temp. $\frac{1}{4}$ sec. post.	
79.72	Intersect line 30 lks. S. of post.	
	S.89*47' W. on a true line between secs. 26 and 35.	