

North Boundary of T. 31 S., R. 7 W., W. M.  
Same Deputy and Contract.

CHAINS

I therefore set at this point, a Laurel post, 4 ft. long, 4 ins. sq. 8 ins. in ground with stone mound 12 ins. high about same. Marked on the NE. side T. 30 S., R. 7 W., S. 32, and T 31 S., R. 7 W. S. 5 on SE., S. 6 on SW., and S. 31 on the NW face of same. Also 5 notches on E. and 1 notch on W. angle of same for the cor. to secs. 5, 6, 31 and 32, from which

A W. Oak, 12 ins. diam., bears N.60\*E., 8 lks. dist.  
Marked T. 30 S., R. 7 W S. 32 B. T.

A Fir, 28 ins. diam., bears S.71\*E., 29 lks. dist.  
Marked T. 31 S., R. 7 W S. 5. B. T.

A Fir, 12 ins diam., bears S.41\*W., 30 lks. dist.  
Marked T. 31S., R. 7 W. S. 6 B. T.

A W. Oak, 8 ins. diam., bears N.33\*W., 57 lks. dist.  
Marked T. 30 S., R. 7 W S. 31 B. T.

Then I run W. on true line along N. boundary of sec. 6.  
Va. 19\*E.

40.00 Set a Maple post 3 ft. long, 3 ins. sq. 18 ins. in the ground, marked  $\frac{1}{2}$ S. on N. side for the  $\frac{1}{2}$  sec. cor. from which

An Alder, 14 ins. diam., bears N.25\*E., 21 lks. dist.  
Marked  $\frac{1}{2}$  S. B. T.

A Maple, 12 ins. diam., bears S58\*E., 27 lks. dist.  
Marked  $\frac{1}{2}$  S., B. T.

77.00 To Tp . cor.  
Land mountainous and broken.  
Soil, rocky 3rd. rate.  
Timber scattering, Fir, Oak, and Pine with thick undergrowth of Fir, Live oak, Balm and Chaperel.  
The land E. of cor. to secs. 5 and 6 steep mountainous broken and rocky. Too steep, to extend the line over, therefore, it was not run.

August 6, 1882.