

Retracement and Survey Portion South Edy., T. 30 S., R. 7 W.

CHAINS

T30S	R7W
S33	S34
S4	S3
T31S	
1918	

from which

A madrona, 10 ins. diam., bears N.41*E., 71 lks. dist.
marked T 30 S R 7 W S 34 B T (New B.T.)

A sugar pine, 20 ins. diam., bears S.7*E., 59 lks. dist.
marked T 31 S R 7 W S 3 B T (Old B.T.)

A madrona, 30 ins. diam., bears S.13*W., 19 lks. dist.
marked T 31 S R 7 W S 4 B T (Old B.T.)

A fir, 30 ins. diam., bears N.47*W., 97 lks. dist.
marked T 30 S R 7 W S 33 B T (Old B.T.)

Thence

West, retracing the line bet. secs. 4 and 33.

Descend NW. slope.

- 2.00 Cow Creek, 175 lks. wide, course NE., ascend.
4.55 fence, bears N. and S.
5.22 Center of S. P. Ry. track, bears N. and S.
5.70 fence, bears N. and S.
12.50 Top of spur, slopes SE., descend.
14.60 Ravine, course SE., ascend steep E. slope.
24.55 Top of point, slopes S^W., descend.
27.50 Ravine, course SW., ascend.
30.10 Top of spur, slopes S., descend.
34.35 Trail, bears NW. and SE.
36.30 Smith creek, 8 lks. wide, course S.60*E.
37.85 Creek, 1 lk. wide, course S.20*E., ascend E. slope.
39.37 Fall 54 lks. S. of the old $\frac{1}{4}$ sec. cor. which is a badly
decayed post, witnessed as described by the surveyor
general. Alongside the old cor.

Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in
the ground for $\frac{1}{4}$ cor. of sec. 33 only, with brass cap
marked

$\frac{1}{4}$ S33
1918