

County Surveyor's Record, Douglas County, Oregon

Retracement and survey portion South Bdy., T. 30 S., R. 7 W.

CHAINS

S.88°18'W., on the S. bdy. of sec. 31.

Ascend through heavy timber and dense undergrowth.

2.77 intersect the old cor. of secs. 5 and 6, T. 31 S., R. 7 W.

located by reference to the old bearing trees., the SE.

tree is now dead. At the exact cor. point

set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the

ground, for angle point, with brass cap marked,

$$\frac{AP}{1918}$$

from which

A fir, 18 ins. diam., bears S.37°W., 31 lks. dist.

marked A P B T (Old B.T.)

A yellow pine, 5 ins. diam., bears N.1°W., 14 lks.

dist. marked A P B T (New B.T.)

Land, mountainous.

Soil, rocky, 3rd. rate.

Timber, pine, fir and oak.

Undergrowth, chaparral and myrtle.

Retracement Subdivisions, T. 30 S., R. 7 W.

From the cor. of secs. 25, 30, 31 and 36, on the W. bdy.
of the Tp.

N.88°27'E., retracing the line bet. secs. 30 and 31.

Descend SE. slope, through heavy timber and dense under-
growth.

0.60 Creek, 1 lk. wide, course SE. ascend.

4.50 Top of spur, slopes S., descend.

8.30 Table Creek, 5 lks. wide, course S., ascend steep SW.
slope.

18.70 Top of spur, slopes SW., along steep S. slope.

43.03 Fall 84 lks. S. of the point for old $\frac{1}{4}$ sec. cor., located
by reference to the bearing trees. At the exact cor.
point.