

County Surveyor's Record, Douglas County, Oregon

West boundary of T. 30 S., R 9 W., W.M.

CHAINS		
	South bet. secs. 31 and 36.	
	Va. 191 ¹ / ₂ *E.	
5.95	A branch, 1 lk. wide, course E.	-50
7.65	A branch, 2 lks. wide, course E.	-50
12.50	Summit of ridge, course E and W.	+125
14.75	A branch, 2 lks. wide, course E.	-50
18.50	A branch, 2 lks. wide, course E.	+60
40.00	Set $\frac{1}{2}$ sec. post, from which	+100
	A Fir, 10 ins. diam., bears S.65*E., 7 lks. dist.	
	A Fir, 12 ins. diam., bears N.40*W., 26 lks. dist.	
72.80	Ascend rocky bluff.	+150
76.50	Summit of mountain.	+150
80.00	Set post, cor Tps. 30 and 31 S., and Rgs. 9 and 10 W.,	
	from which	
	A Fir, 20 ins. diam., bears N.2*E., 67 lks. dist.	
	A Fir, 30 ins. diam., bears S.80*W., 61 lks. dist.	
	A Cedar, 10 ins. diam., bears S.30*E., 55 lks. dist.	
	A Cedar, 10 ins. diam., bears N.40*W., 25 lks. dist.	
	Surface, timber, soil, etc., about the same as last two	
	miles.	
	Aug. 8th, 1855.	
South Boundary of T. 30 S., R 9 W., W.M., same Deputy, Same Contract.		
East on random on South boundary of same Tp., setting mile and half mile posts, six miles, four chs. and fourteen lks. intersect east boundary two chs and forty lks. north of cor. therefore the correction will be south forty lks. and east four chs. and fourteen lks. per mile.		
Thence, N.89*43*W., on true line bet. secs. 36 and 1.		