

30

County Surveyor's Record, Douglas County, Oregon

Retracement of South Boundary of T. 30 S., R. 9 W., W. M.  
As surveyed by William M. Bushey, Deputy Surveyor, under Contract  
No. 613, dated April 29, 1893.

CHAINS

As the south boundary of T. 30 S., R. 9 W., is an old line and the land over which it runs has been burned over several times, which has probably destroyed the cors. and witness trees, I therefore begin at the cor. to Tps. 30 and 31 S., Rgs. 9 & 10 W.

Thence I run

S.89°43'E., bet. secs. 6 and 31.

Var. 19°30'E., at 6:30 A. M.

Descend along the blazed line, 600 ft.

6.00 Top of rocky bluff.

42.06 Set temp. post. I find 2 witness trees, each marked  $\frac{1}{2}$  S. B. T. The post cor. is burned. At cor. point, I set a stone, 12x12x8 ins., 8 ins. in the ground for  $\frac{1}{2}$  sec. cor., marked  $\frac{1}{2}$  on N. face, from which