

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 30 S., R 9 W., W.M.

CHAINS		
	A Hemlock, 12 ins. diam., bears S.74*E., 34 lks. dist., marked T 30 S R 9 W S 4 B T.	
	A Fir, 36 ins. diam., bears S.38*W., 12 lks. dist., marked T 30 S R 9 W S 5 B T.	
	A Hemlock, 15 ins. diam., bears N.74*W., 39 lks. dist., marked T 29 S R 9 W S 32 B T.	
	I measure West to temp. post, 28 lks., which is the dist. I intersect North boundary of township West of this cor.	
	Thence I run S.0*31'E., on a true line bet. secs. 4 and 5.	
	Va. 19*15'E., at 9 A.M.	
	Descend.	-90
8.50	A stream, 1 lk. wide, course NW., enter old burn, dense brush and logs, ascend.	+25
11.25	Descend.	-40
13.80	A stream, 1 lk. wide, course NW., ascend.	+50
21.00	Descend.	-40
25.75	Ascend.	+50
28.75	Descend.	-40
31.50	Ascend.	+100
38.23	Set a Hemlock post, 4 ft. long, 4 ins. sq., 24 ins. in the ground for $\frac{1}{2}$ sec. cor marked $\frac{1}{4}$ S on W face, from which A Hemlock, 5 ins. diam., bears N.74 $\frac{1}{2}$ *W., 21 lks. dist., marked $\frac{1}{4}$ S B T. A Hemlock, 10 ins. diam., bears S.44 $\frac{1}{2}$ *E., 24 $\frac{1}{2}$ lks. dist., marked $\frac{1}{4}$ S B T.	
57.00	Enter heavy timber.	
59.30	Descend.	-40
64.00	Ascend.	+30
71.80	A Fir, 4 ft. diam., on line, marked with 2 notches on N and S sides.	
78.23	The cor. to secs. 4, 5, 8 and 9. Land mountainous, 78.23 chs. Soil 3rd rate. Heavily timbered with fir, hemlock, cedar, maple, dogwood	