

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 30 S., R 9 W., W.M.

CHAINS		
51.00	Descend.	-100
58.95	A spring branch, 1 lk. wide, course East, ascend.	+50
61.00	Descend.	-150
69.00	To south end of lake, 5.00 chs. long, S.20*E., and N.20*W., and 3 chs. wide, I offset N.89*59'W., 4.00 chs., thence on offset line,	
74.20	I offset S.89*59'E., 4 chs. to line, ascend.	+75
79.25	Descend to cor.	-10
80.00	Set a stone, 16x10x10 ins., 12 ins. in the ground for cor. to secs. 17, 18, 19 and 20, marked with 3 notches on S and 5 notches on E edges, from which A Cedar, 16 ins. diam., bears N.81½*E., 39½ lks. dist., marked T 30 S R 9 W S 17 B T. A Fir, 31 ins. diam., bears S.57½*E., 33½ lks. dist., marked T 30 S R 9 W S 20 B T. A Cedar, 32 ins. diam., bears S.24½*W., 54 lks. dist., marked T 30 S R 9 W S 19 B T. A Fir, 10 ins. diam., bears N.24½*W., 70 3/4 lks. dist., marked T 30 S R 9 W S 18 B T. Land mountainous, 80.00 chs. Soil 3rd rate. Heavily timbered with fir, hemlock, cedar, dogwood, myrtle and chinquapin, 80.00 chs. Dense undergrowth of vinemaple, chinquapin, laurel, rhododendron, hemlock, cedar, fir and sallow, 80.00 chs.	
	S.89*38'E., on a random line bet. secs. 17 and 20. Va. 19*E., at 12:30 P.M.	
40.00	Set temp. ¼ sec. cor.	
79.74	Intersect N and S line, 18 lks. south of cor. to secs. 16, 17, 20 and 21. Thence I run N.89*46'W., on a true line bet. secs. 17 and 20. Va. 19*15'E., at 2:15 P.M.	
	Descend	-500
18.30	A Fir, 15 ins. diam., on line marked with 2 notches on E	