

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T 30 S., R 9 W., W.M.

CHAINS	Descend.	-50
4.70	A stream, 1 lk. wide, course S., in bed, 25 lks. wide.	
14.00	Stage barn, south about 6 chs.	
15.00	A stream, 2 lks. wide, course south.	
16.30	A creek bed, 20 lks. wide, course N and S.	
17.55	A trail, course NE and SW., ascend.	+175
40.17	Set a stone, 16x12x6 ins., 12 ins in the ground for $\frac{1}{2}$ sec. cor., marked $\frac{1}{4}$ on N face, from which An Oak, 6 ins. diam., bears N.75*E., 95 lks. dist., marked $\frac{1}{4}$ S B T. An Oak, 12 ins. diam., bears S.59 $\frac{1}{2}$ *E., 141 lks. dist., marked $\frac{1}{4}$ S B T.	
50.00	Descend.	-50
52.25	A rocky ravine, course N and S., ascend.	+75
54.00	Descend.	-75
62.00	A spring branch, 1 lk. wide, course S.	
70.52	A creek bed, course N and S.	
80.33	The cor. to secs. 7, 8, 17 and 18. Land mountainous, 80.33 chs. Soil 4th rate. Heavily timbered with fir, hemlock, cedar, laurel and chinquapin, 15.00 chs. Dense undergrowth of oak, poison oak, vinemaple, chinquapin hazel, laurel, cedar, fir and hemlock, 80.33 chs.	
	N.89*38'W., on a random line bet. secs. 7 and 18. Va. 19*24'E., at 6:15 P.M.	
40.00	Set temp. $\frac{1}{4}$ sec. cor. Sept. 1, 1893	
81.42	Intersect West boundary of the township, 42 lks. north of the cor. to secs. 7, 12, 13 and 18. Thence I run S.89*56'E., on a true line bet. secs. 7 and 18. Va. 19*E., at 7:30 A.M.	