

County Surveyor's Record, Douglas County, Oregon

Resurvey of North Boundary of T. 32 S., R. 1 W.

CHAINS

almost obliterated, from which I find two bearing trees.

A fir, 20 ins. diam., bears S.70*W., 32 lks. dist., mkd. T 32 S R 1 W S 3 B T.

A fir, 24 ins. diam., bears S.12*E., 55 lks. dist., mkd. T 32 S R 1 W S 2 B T.

I destroy the marks on this bearing tree and also the old post, and replace it with a basalt stone, 15x10x5 ins. 10 ins. in the ground for cor. to secs. 34 and 35, mkd. with 2 notches on E. and 4 notches on W. edges. from which

I take two additional bearing trees,

A maple, 6 ins. in diam., bears N.64*E., 52 lks. dist., mkd. T 31 S R 1 W S 35 B T.

A maple, 6 ins. diam., bears N.34*W., 40 lks. dist., mkd. T 31 S R 1 W S 34 B T.

Not finding any error in my work, I continue the line on West from cor. to secs. 34 and 35.

44.00 A point about 100 ft. above sec. cor. and descend hill, bears N. and S.

50.33 A point about 300 ft. below point of descent, and North fork of Elk Creek, 15 lks. wide, runs S.80*W.

77.63 A point on line where the old 1/4 sec. cor. on S. bdy. of sec. 34, bears South, 193 lks. dist., which is a post greatly decayed with two bearing trees still standing.

As T. 31 S., R. 1 W. has been subdivided, I could not change the location of this cor. I, therefore, destroyed the old post and replaced it with a basalt stone, 14x8x8 ins. 10 ins. in the ground, mkd. 1/4 on N. face. from which

A laurel, 9 ins. diam., bears S.20*E., 17 lks. dist., mkd. 1/4 S B T.