

County Surveyor's Record, Douglas County, Oregon

Resurvey of North Boundary of T. 32 S., R. 1 W.

CHAINS

from which

A fir, 28 ins. diam., bears N.45*E., 45 lks. dist.,
mkd. T 31 S R 1 W S 34 B T.

A maple, 12 ins. diam., bears N.25*W., 30 lks. dist.,
mkd. T 31 S R 1 W S 33 B T.

A fir, 40 ins. diam., bears S.40*E., 45 lks. dist.,
mkd. T 32 S R 1 W S 4 B T.

An alder described in field notes of original sur-
has fallen.

The three bearings trees were newly marked.

I then continue the line West from this sec. cor.

38.00 Elk Creek, 30 lks. wide, runs NW.

42.76 Elk Creek, 30 lks. wide, runs SW.

45.26 Elk Creek, 30 lks. wide, runs N.70*W., and descend

77.76 A point, about 300 ft. above Elk Creek, where the old
1/4 sec. cor. on S. bdy. of sec. 33, bears South 178
lks. dist., which is a decayed post, with 1 bearing
tree still standing.

I destroyed this post and replaced it with a basalt stone
14x10x8 ins. 10 ins. in the ground, mkd. 1/4 on N.
face.

from which

A cedar, 40 ins. diam., bears S.15*W., 52 lks. dist.,
mkd. 1/4 S B T.

A fir, 36 ins. diam., bears N.3*E., 29 lks. dist.,
mkd. 1/4 S B T.

The cedar is the one described in field notes of original
survey and was newly marked.

80.00 A point, 2.24 chs. West of 1/4 sec. cor. and set a basalt
stone, 18x11x8 ins. 12 ins. in the ground, for cor. to
secs. 4 and 5, mkd. with 4 notches on E. and 2 notches
on W. edges.

from which