

Retracement of a Portion of the East Bdy. of T. 31 S. R. 2 W.

CHAINS

1/4 sec. cor. mkd. 1/4 on W. face, from which

A cedar, 18 ins. diam., bears N.10\*E., 15 lks. dist.,  
mkd. 1/4 S 31 B T.

A cedar, 28 ins. diam., bears S.47\*W., 22 lks. dist.,  
mkd. 1/4 S 36 B T.

The course of this line is N. and the distance is 40.25  
chs.

Commencing at the 1/4 sec. cor. I run

North, bet. secs. 31 and 36.

3.00 Rock bluff, 40 ft. perpendicular.

40.50 The cor. of secs. 25, 30, 31 and 36.

This cor. is nearly obliterated. The only remaining traces  
being two of the bearing trees, deeply overgrown.

I re-establish the cor in its original position as follows:

Set an ironstone, 15x10x6 ins. 10 ins. in the ground, for  
cor. of secs. 25, 30, 31 and 36, mkd. with 5 notches on  
N. and 1 notch on S. edge, from which

A cedar, 28 ins. diam., bears N.5\*E., 9 lks. dist.,  
mkd. T 31 S R 1 W S 30 B T. *Old B.T.*

A madrone, 10 ins. diam., bears S.45 1/2 \*E., 57 lks. dist.,  
mkd. T 31 S R 1 W S 31 B T.

A fir, 20 ins. diam., bears S.8\*W., 70 lks. dist.,  
mkd. T 31 S R 2 W S 36 B T.

A yellow pine, 16 ins. diam., bears N.22\*W., 34 lks.  
dist., mkd. T 31 S R 2 W S 25 B T.

The course of this line is North and the distance is  
40.50 chs.

Land, mountainous.

Soil, clay, loam and stony, 2nd and 3rd rate.

Timber, fir, cedar, pine, madrone.

Undergrowth, hazel, vine maple and fir.

Mountainous or heavily timbered land or land covered with  
dense undergrowth and exceptionally difficult to survey.

80.75 chs.

Oct. 28, 1906.