

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of Portion of Subdivisional Lines  
in T. 31 S., R. 1 W.

CHAINS

T31S	R1W
S27	S26
<hr/>	
S34	S35
1923	

from which

- A fir, 12 ins. diam., bears N.30\*E., 36 lks. dist.,  
mkd. T 31 S R 1 W S 26 B T. (Old B.T.)
- A fir, 36 ins. diam., bears S.10\*E., 38 lks. dist.,  
mkd. T 31 S R 1 W S 35 B T. (Old B.T.)
- A fir, 24 ins. diam., bears S.38\*W., 11 lks. dist.,  
mkd. T 31 S R 1 W S 34 B T. (Old B.T.)
- A fir, 20 ins. diam., bears N.50\*W., 56 lks. dist.,  
mkd. T 31 S R 1 W S 27 B T. (Old B.T.)

Land, mountainous.

Soil, 3rd rate.

Timber, fir, cedar, oak and pine.

Undergrowth, vine maple, hazel and live oak.

S.89\*37'W., on a true line, bet. secs. 27 and 34.

Over mountainous land, through heavy timber and dense  
undergrowth.

Asc. 197 ft. over SE. slope.

8.50 Spur, slopes SW.; desc. 375 ft. over W. slope.

16.65 Trail, bears NE. and SW.

39.88 Fence, bears N. and S.

40.00 Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the  
ground, for 1/4 sec. cor. of sec. 27 only, with brass  
cap marked

$\frac{1}{4}$ S27
<hr/>
1923

from which

- A fir, 7 ins. diam., bears N.27\*E., 30 lks. dist.,  
mkd. 1/4 S 27 B T.