

County Surveyor's Record, Douglas County, Oregon

Retracement of the South Boundary of T. 31 S., R. 2 W.

CHAINS

39.56

The Qr. Sec. cor. on South Bdy. sec. 31, which is an ironstone 5x10x6 ins. above ground, firmly set, marked and witnessed as described by the surveyor general.

Commencing at the Qr. sec. cor., I retrace

S.89°58'W., on S. bdy., sec. 31..

14.10

The closing cor. of Tps 31 S., R. 2 W., and 32 S R 3 W on the East Bdy. of T. 31 S., R. 3 W established by me under Contract No. 757 which is a fir post 4 ins. sq., 12 ins. above ground, firmly set and marked T.31 S., R. 2 W S 31 on N, C.C on E, and T. 32 S., R 3 W., S 1 on S with 6 grooves on N & E faces from which

A fir, 24 insl diam., bears N.42°E., 36 lks. dist., mkd. T 31 S, R 2 W S 31 E T.

A fir, 18 ins. diam., bears S.43°E., 42 lks. dist., mkd. T 32 S R. 3 W S 1 E T.

October 24, 1906.

Retracement of W. Bdy. of T. 31 S., R., 2 W., same Deputy and Contract.

Thence I run

South, on E. bdy., sec. 1, T. 31 S., R. 3 W.

Over mountainous land heavily timbered and covered with dense undergrowth.

Along NE slope.

9.75 Creek 1 lk. wide, course N.60°E.

10.25 The closing cor. of T. 30 & 31 S., R. 2 W.

21.75 Creek 2 lks. wide, course N.30°E.

Ascend North slope.

57.31 The Qr. sec. cor. nearly obliterated.

The cor. tree is dead and decaying.

I reestablish the cor. in its original position for sec.

1, T. 31 S., R. 3 W., only as follows:

No stones obtainable.

Set madrone post, 3 ft. long, 4 ins. sq., 24 ins. in the ground for qr. sec. cor. on W. bdy. sec. 1, marked qr. on W face, from which

A madrone, 8 ins. diam., bears N.41 $\frac{1}{2}$ °W., 41 lks. dist.