

County Surveyor's Record, Douglas County, Oregon

Retracements of the West Boundary of T. 31 S., R. 2 W.

CHAINS

A Fir, 15 ins. diam., bears S.55*W., 8 lks. dist.
Marked $\frac{1}{4}$ S 12 B T

The course of this line is South and the distance is
39.75 chs.

Commencing at the $\frac{1}{4}$ sec. cor. I run
South on East Boundary sec. 12

22.00 Creek, 1 lk. wide, course East

32.00 Ridge bears E & W

37.29 The closing cor. of secs. 7 & 18

39.15 The cor. of secs. 12 & 13 T. 31 S., R. 3 W.

The course of this line is South and the distance is 39.15
chs.

Land Mountainous

Soil, Granite, loam and stony, 3rd. rate

Timber, Fir, Hemlock, Cedar

Undergrowth, Madrone, Hazel and Hemlock

Mountainous or heavily timbered land

Land covered with dense undergrowth and exceptionally
difficult to survey. 78.80 chs.

July 5, 1908

Thence I run

South on East Boundary sec. 13

Over Mountainous land, heavily timbered and covered with
dense undergrowth

Along NE slope

0.50 Creek, 1 lk. wide, course N.20*E.

500 Ridge bears E & W

Along SE slope

18.00 Creek, 1 lk. wide, course N.20*E.

40.98 The $\frac{1}{4}$ sec. cor. partially obliterated bears East 27 lks.
dist.

The Post has decayed at the bottom and fallen down