

## County Surveyor's Record, Douglas County, Oregon

## Retracement of the West Boundary of T. 31 S., R. 2 W.

CHAINS	
22.50	Creek, 1 lk. wide, course NE
41.52	The $\frac{1}{4}$ sec. cor. which is a post, greatly decayed, marked and witnessed as described by the surveyor general I reestablish this cor. in its original position for sec. 24 T. 31 S., R. 3 W., only as follows No stones obtainable Set a Fir Post 3 ft. long, 4 ins. sq. 24 ins. in the ground for $\frac{1}{4}$ sec. cor. on West Boundary sec. 24 marked $\frac{1}{4}$ on W face from which A Madrone, 12 ins. diam., bears N.66*W., 39 lks. dist Marked $\frac{1}{4}$ S 24 B T A Madrone, 8 ins. diam., bears S.13*W., 8 lks. dist. Marked $\frac{1}{4}$ S 24 B T The course of this line is South and the distance is 41.52 chs. Commencing at the $\frac{1}{4}$ sec. cor. I run South on West Boundary sec. 24
8.50	Divide bet. Hatchet and Callahan Creeks bears NE & SW Descend SE slope
35.25	The closing cor. of secs. 19 & 30
40.19	The cor. of secs. 24 & 25 T. 31 S., R. 3 W. The course of this line is South and the distance is 40.19 chs. Land Mountainous Soil, Loam and stony 3rd. rate Timber, Fir, Hemlock, Cedar Undergrowth Hemlock, Madrone Hazel Mountainous or heavily timbered land Land covered with dense undergrowth and exceptionally difficult to survey. 81.71 chs.

July 6, 1908

12/79

ORIG. HAND WRITTEN

NOTES CONFIRMED

READS "W" BUT I

FEEL IT

SHOULD BE

EAST

J. R.