

County Surveyor's Record, Douglas County, Oregon

Retracement of the West Boundary of T. 31 S., R. 2 West

CHAINS	<p>Land Mountainous</p> <p>Soil, stony, 3rd. rate</p> <p>Timber, Fir, Hemlock, Cedar</p> <p>Undergrowth Madrone, Lilac, hemlock, and Hazel</p> <p>Mountainous or heavily timbered land or land covered with dense undergrowth and exceptionally difficult to survey</p> <p>81.51 chs.</p>
2.50	<p>South on East Boundary sec. 36 T. 31 S., R. 3 W.</p> <p>Over Mountainous land, through scattering Timber and dense undergrowth</p> <p>Along East slope</p> <p>Creek, 3lks. wide, headwaters of Callahan Creek, course NE</p> <p>Ascend NW slope</p>
33.70	<p>Creek, 1 lk. wide, course NW</p>
40.95	<p>The $\frac{1}{4}$ sec. cor. which is a granite stone 5x12x10 ins. above ground firmly set, marked and witnessed as described by the surveyor general</p> <p>I reestablish this cor. in its original position for sec. 36 T. 31 S., R. 3 W., only as follows</p> <p>A Granite stone 5x12x10 ins. above ground already set for $\frac{1}{4}$ sec. cor. on East Boundary sec. 36 T., 31 S., R. 3 W.,</p>