

## County Surveyor's Record, Douglas County, Oregon

Resurvey of South Boundary of T. 31 S., R. 2 W.  
Same Deputy and Contract

CHAINS	
	Thence I run
	N.89*58'E., on South Boundary of sec. 31 T 31 S., R. 2 W
	Over Mountainous land, heavily timbered and covered with dense undergrowth.
	Descend E slope
2.50	Creek, 2 lks. wide, course SE
	Along S slope
8.50	Ravine, course South
9.63	Set a slate stone 18x10x8 ins., 12 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on North face from which
	An Alder, 8 ins. diam., bears N.14*E., 93 lks. dist.
	Marked $\frac{1}{4}$ S 31 B T
	A Fir, 18 ins. diam., bears N.79*W., 52 lks. dist.,
	Marked $\frac{1}{4}$ S 31 B T
14.10	The old $\frac{1}{4}$ sec. cor. on South Boundary sec. 31
	I destroy the cor. and marks on bearing trees
15.50	The closing cor. of T. 32 S., Rs. 2 & 3 W.
	Ascend SW slope
49.63	The closing cor. of secs. 31 & 32
	Land Mountainous
	Soil, Granite, 3rd. rate
	Timber, Fir, Hemlock, Cedar; undergrowth, Lilac, Madrone
	Hazel
	Mountainous or heavily timbered land or land covered with dense undergrowth and exceptionally difficult to survey.
	49.63 chs.
	N.89*58'E., on South Boundary sec. 32
	Over Mountainous land, heavily timbered and covered with dense undergrowth
2.50	Divide bet. Cow Creek and Elk Creek bears NW & SE
	Descend NE slope
4.03	The old cor. of secs. 31 & 32
	I destroy the cor. and marks on bearing trees
9.25	Ridge Point descending NE
16.75	Ravine, course NE