

Resurvey of South Boundary of T. 31 S., R. 2 W.

CHAINS	<p>Ascends NW slope</p> <p>27.00 Elbow ridge bears S.30*E., and S.60*W.</p> <p>Descend NE slope</p> <p>39.75 Set a Granite stone 15x12x6 ins. in the ground for <math>\frac{1}{4}</math> sec. cor. marked <math>\frac{1}{4}</math> on W face from which</p> <p style="padding-left: 40px;">A Fir, 20 ins. diam., bears N.30*E., 77 lks. dist.</p> <p style="padding-left: 40px;">Marked <math>\frac{1}{4}</math> S 32 B T</p> <p style="padding-left: 40px;">A Madrone, 12 ins. diam., bears N.57<math>\frac{1}{2}</math>*W., 54 lks. dist., Marked <math>\frac{1}{4}</math> S 32 B T</p> <p>42.31 The old <math>\frac{1}{4}</math> sec. cor., I destroy the cor. and marks on bearing trees</p> <p>43.91 The closing cor. of secs. 5 &amp; 6 T. 32 S., R. 2 W. Thence N.89*49'E.</p> <p>47.50 Creek, 4 lks. course N.60*E.</p> <p>Along North slope</p> <p>75.00 Ridge Point descending N.60*E.</p> <p>Descend E slope</p> <p>79.50 The closing cor. of secs. 32 &amp; 33</p> <p>Land Mountainous</p> <p>Soil, Granite and stony, 3rd. rate</p> <p>Timber, Fir, Cedar, Madrone</p> <p>Undergrowth, Hazel, Vinemaple</p> <p>Mountainous or heavily timbered land, or land covered with dense undergrowth and exceptionally difficult to survey</p> <p>79.50 chs.</p> <p style="text-align: right;">July 8, 1908</p>
	<p>Thence I run</p> <p>N.89*49'E., on South Boundary sec. 33</p> <p>Over Mountainous land, heavily timbered and covered with dense undergrowth</p> <p>Descend E slope</p> <p>6.86 The old cor. of secs. 32 &amp; 33</p> <p>I destroy the cor. and marks on bearing trees</p> <p>7.75 Drew Creek trail bears NE &amp; SW</p> <p>9.30 Drew Creek, 10 lks. wide, course NE</p> <p>Ascend NW slope</p>